## TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer)

Name of School

PALGHAT LIONS SCHOOL

1 Name of Officer

: BHAGIRATHI CS (Asst.Engineer)

2 Location

: Koppam, Palakkad

3 Period which the certificate is issued:

2024-25

4 Type of Building

RCC Roof Main Block GF - 479.30 m2 FF - 479.30 m2, SF - 479.30 m2

NIL

Block 2 - GF - 248.53 m2, FF - 248.53 m2 Block 3 - GF - 896.95 m2, FF - 896.95 m2

5 Nature of defect if any

a) Foundation and Basement

b) Super Structure

c) Doors and Windows

d) Wood work Wrought & put up

e) Roof

f) Flooring

g) Miscellaneous

6 Any Major defects noticed which will render the building unsafe in any

manner

: NIL

7 Whether maintanance work have been

done

: YES

Whether the structure is sound for conducting classes

: YES, Structure is safe under normal wind and weather condition to conduct classes

Note

(1) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

(2) Any additional observations, if deemed necessary for the certificate may be furnished separatly with the certificate.

Certified that the school was inspected by me on 07/05/2024 and found fit to conduct classes for the period 2024-25 for the reasons stated above.

Place:Palakkad Date:08/05/2024



Designation Assistant Engineer
Palakkad Municipality